



use Kaspersky QR Scanner to VERIFY paper. [App Store & Google Play](#)
<http://jpcenter.ru/r-ZGE20-6014850-dsIPw5rIAsttMcUwZZ>



TRUE REPORT

ZGE20-6014850


Lot number	80445
Auction name	USS Tokyo
Auction date	2016-04-21
Chassis ID	ZGE20W
Brand	TOYOTA
Model	WISH
Mileage	32 000 km
Engine CC	1800
Year	2014
Details	5D
Grade	1.8S
Inspection	2017.07
Equipment	***
Transmission	AT
Start price	100 000 JPY
Finish price	620 000 JPY
Color	BLUE id=3
Condition	***
Status	sold



use Kaspersky QR Scanner to VERIFY paper. [App Store](#) & [Google Play](#)
<http://jpcenter.ru/r-ZGE20-6014850-dsIPw5rIASuttMcUwZZ>



事故現状車コーナー

No. 80445	車種 (自動車以外は記入) 排気量	1800	型式	DBA-ZGE20W	評価点
	初年度登録年月 車名	2017年 ウィッシュ	グレード	SD 1.8S	4WD
車検	29年 7月	シフト	AT	燃料	ガソリン
走行	31,797 km	冷房	有	新車検定済	有
外色	青	カラーNo	8V9	新車検定済	有
燃料	ガソリン・軽油	内装色		車検変更期限	
車検	29年 7月	輸入区分	ディーラー並行	ハンドル	左・右
リサイクル 預託金	10460円	車検定済	7人	登録地	長野 301 (19609)
注意事項 (検定・不具合箇所および状態等)		車台番号 ZGE20-6014850			
E315701 Ambagok		シリアルNo			
後部付 Drivable		無効			
検査員報告 (USS使用欄)					
F 現状					
[荷台内寸] 約 長さ 460 cm x 幅 172 cm x 高さ 154 cm (車検証上の寸法)					



Auction list explanation

A1 Small Scratch

A2 Scratch

A3 Big Scratch

E1 Few Dimples

E2 Several Dimples

E3 Many Dimples

U1 Small Dent

U2 Dent

U3 Big Dent

W1 Repair Mark/Wave (hardly detectable)

W2 Repair Mark/Wave

W3 Obvious Repair Mark/Wave (needs to be repainted)

S1 Rust

S2 Heavy Rust

C1 Corrosion

C2 Heavy Corrosion

X Need to be replaced

XX Replaced

B1 Distortion on (radiator) core support or back panel (approximately size of a thumb)

B2 Big Distortion on (radiator) core support or back panel

Y1 Small Hole or Crack

Y2 Hole or Crack

Y3 Big Hole or Crack

X1 Small Crack on Windshield (approximately 1cm)

R Repaired Crack on Windshield

RX Repaired Crack on Windshield (needs to be replaced)

X Crack on Windshield (needs to be replaced)

B Dent with scratch

P Paint marked

H Paint faded

G Stone chip in glass