



use Kaspersky **QR Scanner** to VERIFY paper. <u>App Store & Google Play</u> http://jpcenter.ru/r-NZT260-3154039-dsIPw5pefntRgwhk4R8



TRUE REPORT


	NZT260-3154039
Lot number	30531
Auction name	CAA Chubu
Auction date	2014-12-10
Chassis ID	NZT260
Brand	TOYOTA
Model	PREMIO
Mileage	0
Engine CC	1500
Year	2014
Grade	F EX PACKAGE
Equipment	AAC
Transmission	FAT
Awd	0
Start price	1230 000 JPY
Finish price	1930 000 JPY
Color	BLACK id=2
Condition	\$
Status	unsold





use Kaspersky **QR Scanner** to VERIFY paper. <u>App Store & Google Play</u> http://jpcenter.ru/r-NZT260-3154039-dslPw5pefntRgwhk4R8











Auction list explanation

A1 Small Scratch X Need to be replaced
A2 Scratch XX Replaced

A3 Big Scratch

B1 Distortion on (radiator) core support or back panel (approximately size of a thumb)

E1 Few Dimples B2 Big Distortion on (radiator) core support or back panel

E2 Several Dimples Y1 Small Hole or Crack
E3 Many Dimples Y2 Hole or Crack
U1 Small Dent Y3 Big Hole or Crack

U2 Dent X1 Small Crack on Windshield (approximately 1cm)

U3 Big Dent R Repaired Crack on Windshield

W1 Repair Mark/Wave (hardly detectable) RX Repaired Crack on Windshield (needs to be replaced)

W2 Repair Mark/Wave X Crack on Windshield (needs to be replaced)

W3 Obvious Repair Mark/Wave (needs to be repainted)

B Dent with scratch

S1 Rust

P Paint marked

S1 Rust P Paint marked
S2 Heavy Rust H Paint faded
C1 Corrosion G Stone chip in glass

C2 Heavy Corrosion